

Site Photographs



Photo 1 - Existing building entrance - shown from Highland Street



Photo 2 - Existing building face - north east side

Site Photographs



Photo 3 - Existing site entrance and parking - Highland Street in right side of photo




Photo 4 - Existing site area for proposed building expansion - shown from Highland Street

Site Photographs



Photo 5 - Existing site entrance and parking - Highland Street in left side of photo



Photo 6 - Existing trees located within the proposed building footprint to be removed

Site Photographs



Photo 7 - Existing landscaping along the rear property line - Residential Abutters (facing west)



Photo 8 - Existing landscaping along the rear property line - Residential Abutters (facing south)

Site Photographs



Photo 9 - Existing concrete pad to be removed and replaced with loam and seed



Photo 10 - Existing concrete walk to be removed.